

# Product Safety Recall



Ⓔ BOSCH 0 986 479 V29 MIN. TH. 25.0 (250) (25A) 853241591

Part Number: 0 986 479 V29



Manufacture code identification: 717 to 956



## Bosch Brake Disc Rotors

Designed for fitment on the front axle of selected Holden Colorado and Isuzu D-Max models manufactured from 2011.

**Part number 0986479V29** with manufacturing dates from January 2017 - August 2019 (numbers **717 - 956**)

**Defect:** Cracking of the brake disc rotor hub (Product) may occur in some instances where the wall thickness in the neck area is thinner than expected.

**Hazard:** If the Product cracks the vehicle could experience reduced braking capacity which may increase the risk of an accident occurring.

**What to do:** Consumers should stop using the potentially defective Product, including vehicles fitted with the Product:

- For vehicles fitted with the Product, consumers should return the vehicle to the vehicle dealer or to the store which fitted the Product.
- Products not fitted to a vehicle may be returned for a full refund.

**Contact details:** Robert Bosch (Australia) Pty Ltd on 0800 543 356 (New Zealand), email: [BoschService.NetworkWebsiteEnquiry@au.bosch.com](mailto:BoschService.NetworkWebsiteEnquiry@au.bosch.com)

### New Zealand Importer/Distributor

Holden New Zealand Limited  
2/118 Savill Drive, Mangere East, Auckland 2024  
Phone: 09 886 0826

See [www.recalls.govt.nz](http://www.recalls.govt.nz) for  
other New Zealand consumer product recalls